

# MATERIAL SAFETY DATA SHEET

## INSIDE CPE CORNERS

### 1. General

<b>Trade Name</b>	INSIDE CPE CORNERS	<b>Date Prepared</b>	05/01/10
<b>Manufacturer's Name</b>	THE NOBLE COMPANY		
<b>Address</b>	7300 Enterprise Drive Spring Lake, MI 49456		
<b>Emergency Telephone Number</b>	(231) 799-8000		
<b>Telephone Number for Information</b>	(231) 799-8000		
<b>DOT Hazard Classification</b>	NON-HAZARDOUS		

### 2. Hazardous Ingredients/Identity Information

Hazardous Components (Specific Chemical Identity; Common Names(s))	ACGIH TLV	OTHER LIMITS RECOMMENDED	% (optional)
BARIUM	0.5 MG / M3	AS BARUIM	< 0.1 %
*TOXIC CHEMICAL AS DEFINED BY OSHA, 29 CFR 1910, 1200 AND SUBJECT TO THE REPORTING REQUIREMENTS OF SEC. 313 OF TITLE III OF THE SUPERFUND AMENDMENTS AND REAUTHORIZATION ACT OF 1986 AND 40 CFR PART 372.			
<b>NOTE:</b> THRESHOLD LIMIT VALUES ARE FOR AIRBORNE DUST OR MIST NOT APPLICABLE TO SHEET GOODS.			

### 3. Physical/Chemical Characteristics

<b>Boiling Point</b> N/A	<b>Specific Gravity (H<sub>2</sub>O = 1)</b> 1.29	<b>Vapor Pressure (mm Hg.)</b> N/A	<b>Melting Point</b> N/A
<b>Vapor Density (AIR = 1)</b> N/A	<b>Evaporation Rate ( Butyl Acetate = 1 )</b> NONE	<b>Solubility in Water</b> INSOLUBLE	
<b>Appearance and Odor</b>	FABRIC COVERED OPAQUE PIGMENTED SHEET		
<b>VOC Statement:</b>	ZERO VOC'S (calculated)		

### 4. Fire and Explosion Hazard Data

<b>Flammable Limits</b> N/A
<b>Special Fire Fighting Procedures</b> WEAR SELF-CONTAINED POSITIVE PRESSURE BREATHING APPARATUS
<b>Unusual Fire and Explosion Hazards</b> BURNING PRODUCT LIBERATES HCL GAS

**5. Reactivity Data**

<b>STABILITY</b>	Unstable	<b>Conditions to Avoid</b>
	Stable X	COMBUSTION LIBERATE HCL GAS

**Incompatibility (Materials to Avoid)**  
HCL, CO<sub>2</sub>, CO

<b>Hazardous Polymerization</b>	May Occur
	Will Not Occur X

**6. Health Hazard Data**

**Health Hazards (Acute and Chronic)**  
CONTAINS PVC WHICH MAY CONTAIN VINYL CHLORIDE MONOMER, A CANCER SUSPECT AGENT. CHECK OSHA VCM REGULATION 29 CFR, TITLE 29, CHAPTER XVII PART 1910.

**Signs and Symptoms of Exposure**  
BASED ON AVAILABLE DATA, REPEATED EXPOSURES ARE NOT ANTICIPATED TO CAUSE ANY SIGNIFICANT EFFECTS.

**7. Precautions for Safe Handling and Use**

**Steps to Be Taken in Case Material Is Released or Spilled**  
RETURN TO CONTAINER, VACUUM, SWEEP OR SHOVEL UP.  
NOT CLASSIFIED AS A HAZARDOUS WASTE UNDER BCRA.

**Waste Disposal Method**  
BURN IN ADEQUATE INCINERATOR OR BURY IN LANDFILL IN ACCORDANCE WITH APPLICABLE FEDERAL, STATE AND LOCAL REGULATIONS.

**Precautions to Be Taken in Handling and Storing**  
N/A

**Other Precautions**  
AVOID BREATHING VAPORS WHEN CEMENTING WITH SOLVENTS

**8. Control Measures**

**Respiratory Protection (Specify Type)**  
SELF-CONTAINED BREATHING APPARATUS IN PRESENCE OF BURNING MATERIAL

<b>VENTILATION</b>	<b>Local Exhaust</b>	<b>Special</b>
	GOOD AIR EXCHANGE IN WORK PLACE	AVOID BREATHING DECOMPOSITION PRODUCTS

<b>Protective Gloves</b>	<b>Eye Protection</b>
N/A	USE SAFETY GLASSES

**Other Protective Clothing or Equipment**  
N/A

**Work/Hygienic Practices**  
WASH WITH SOAP AND WATER AFTER HANDLING

THE INFORMATION PRESENTED HEREIN, WHILE NOT GUARANTEED, WAS PREPARED BY TECHNICALLY KNOWLEDGEABLE PERSONNEL AND TO THE BEST OF OUR KNOWLEDGE IS TRUE AND ACCURATE. IT IS NOT INTENDED TO BE ALL-INCLUSIVE, AND THE MANNER AND CONDITIONS OF USE AND HANDLING MAY INVOLVE OTHER OR ADDITIONAL CONSIDERATIONS. CONSULT NOBLE MANUFACTURING COMPANY FOR FURTHER INFORMATION.